<u>SPEED INDICATOR DEVICE (SID) REPORT - DARSHAM</u> <u>16 September to 11 October 2022</u>

The following figures are for the period 16 September to 11 October 2022 measuring eastbound traffic along The Street in the SID's original location. There is not yet a full four-week set of data.

DESCRIPTION	NUMBER	% OF TOTAL	NOTES
Total number of vehicles recorded by SID travelling east on The Street, beyond Priory Lane	13018	N/A	Average of 3719 vehicles per week, which is roughly the same as the last set of measurements at this location.
Total number of vehicles within the speed limit (30 mph)	9922	76.2%	Up 1.2% on previous report.
Total number of vehicles exceeding the speed limit (30 mph)	3096	23.8%	Down 1.2% on previous report.
Total number of vehicles exceeding 35 mph	620	4.8%	Largely unchanged on previous report.
Total number of vehicles exceeding 40 mph	87	0.7%	Largely unchanged on previous report.
Total number of vehicles exceeding 45 mph	20	0.15%	Largely unchanged on previous report.
Total number of vehicles exceeding 50 mph	4	0.03%	Largely unchanged on previous report.
Total number of vehicles travelling below 24 mph	3919	30%	The mean speed of vehicles is above 24 mph, meaning that we would not meet the criteria for reducing the speed limit to 20 mph at this location.

Trends and observations

- Compliance with the speed limit has improved slightly at this location.
- Excessive speeding remains a concern at this location. There is no clearly identifiable pattern, other than that speeding predominantly occurs <u>during the day</u>, rather than at night as might be expected. In fact, three of the four speeding violations in excess of 50 mph occurred between 09:00 and 11:00 in the morning.
- The data collected would **not** support a reduction in the speed limit 20 mph **at this location**, but there is still solid evidence and support for a reduction in the speed limit to 20 mph further into the village.