

SPEED INDICATOR DEVICE (SID) REPORT - DARSHAM

1 November to 31 December 2022

The following figures are for the period 1 November to 31 December 2022 (a two-month period) measuring eastbound traffic along The Street in the SID's location off the A12.

DESCRIPTION	NUMBER	% OF TOTAL	NOTES
Total number of vehicles recorded by SID travelling east on The Street from the A12	28489	N/A	<i>Average of 3165 vehicles per week, which is a further decrease of 10% compared to the last report and 20% decrease since the summer.</i>
Total number of vehicles within the speed limit (30 mph)	22288	78.2%	<i>Improved on previous report.</i>
Total number of vehicles exceeding the speed limit (30 mph)	6201	21.7%	<i>Improved on previous report.</i>
Total number of vehicles exceeding 35 mph	1119	3.9%	<i>Improved on previous report.</i>
Total number of vehicles exceeding 40 mph	156	0.6%	<i>Slight improvement on previous report.</i>
Total number of vehicles exceeding 45 mph	36	0.1%	<i>Improved on a per-month basis. One-third of these incidents occurred between 17.12 and 31.12, mostly in the afternoon.</i>
Total number of vehicles exceeding 50 mph	5	0.02%	<i>Generally improved. Incidents were recorded on 14.11 at 21:50, 28.11 at 05:25, 4.12 at 16:30, 26.12 at 11:25, and 31.12 at 09:25.</i>
Total number of vehicles travelling below 24 mph	9301	32.6%	<i>The mean speed of vehicles is above 24 mph, meaning that we would not meet the criteria for reducing the speed limit to 20 mph at this location.</i>

Trends and observations

- Compliance with the speed limit has improved marginally and remains largely good.
- There is still no clearly identifiable pattern to incidents of excessive speed, other than that speeding predominantly occurs during the day, rather than at night as might be expected.
- The data collected would **not** support a reduction in the speed limit 20 mph **at this location**, but there is still solid evidence and support for a reduction in the speed limit to 20 mph further into the village.