

**SPEED INDICATOR DEVICE (SID) REPORT - DARSHAM**  
**27 July to 15 September 2022**

The following figures are for a seven-week period, from 27 July to 15 September 2022, measuring **eastbound** traffic on The Street just before Priory Lane. Data is absent for the period 11 July to 27 July due to the failure of the SID to measure correct data when facing west at this location.

DESCRIPTION	NUMBER	% OF TOTAL	NOTES
Total number of vehicles recorded by SID travelling east on The Street, beyond Priory Lane	<b>13625</b>	<b>N/A</b>	<i>Average of 1946 vehicles per week, which is roughly 200 vehicles per week <b>fewer</b> than the previous report (roughly 10% fewer vehicles).</i>
Total number of vehicles <b>within</b> the speed limit (30 mph)	<b>13411</b>	<b>98.4%</b>	<i>Largely unchanged on previous report.</i>
Total number of vehicles <b>exceeding</b> the speed limit (30 mph)	<b>240</b>	<b>1.8%</b>	<i>Slightly up on previous report.</i>
Total number of vehicles <b>exceeding 35 mph</b>	<b>32</b>	<b>0.2%</b>	<i>Largely unchanged on previous report.</i>
Total number of vehicles <b>exceeding 40 mph</b>	<b>4</b>	<b>0.03%</b>	<i>No vehicles recorded exceeding 40 mph at this location in last report.</i>
Total number of vehicles <b>exceeding 45 mph</b>	<b>0</b>	<b>0%</b>	<i>No change.</i>
Total number of vehicles <b>exceeding 50 mph</b>	<b>0</b>	<b>0%</b>	<i>No change.</i>
Total number of vehicles travelling <b>below 24 mph</b>	<b>11074</b>	<b>81.3%</b>	<i>The mean speed of vehicles is well below 24 mph, meaning that we continue to meet one of the criteria for reducing the speed limit to 20 mph.</i>

**Trends and observations**

- Compliance with the speed limit remains good at this location.
- Three of the four vehicles recorded speeding in excess of 40 mph were recorded between 13 and 15 September, which suggests they were committed by the same vehicle.